Feuchtigkeitsmessgeräte
# Moisture Meter
Humidimètre

Online Continuous Moisture Measurement

**display and controlling unit
AD-AT058**

alarm signal
output 0 - 20mA

power supply
24VDC

**contactless capacitive
moisture sensor
DKM 50x20**

- turning knob for adjusting of measuring parameters
  e.g. material selection, threshold values, measuring range, …
- teach function for quick calibration with on or more comparing measurements
- special algorithm for moisture determination average values,
  elimination of knotholes and cracks
- alarm signal or analogue output signal
- optional customer specific solutions
- contactless moisture sensors
- height adjustable sensors
- average moisture measurement till 10 cm depth
- different sensor sizes available, fitting to the wished measurement