

Test Modul PE35-7



The test module PE35-7 can be used for testing and calibrating of our capacitive moisture meter DM7-AL and DS7U.

ATTENTION:

Have a look to the sensor, it has to be clean and dry.

The Testmodul PE30-7 must not be on a metal surface, please put it on an isolated surface like plastic.

The metal frame must not be touched during test measurements!

Using:

Hold the instrument into the air and switch it on.

Adjust the mentioned material setting. Press the sensor on the testmodule as shown in the above picture. the sensor into the test module, hold the sensor with the testmodule free into the air, read of the display value and compare it with the rated value.

meter type	adjustment	rated value	comment:
DM7-AL	Input value	250±5	
DS7U	Input value	250±5	